

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 6-7W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 1-6

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 10-29-64

WITNESSES TO CORNER..... 12" W. Spruce (1/2 S NBT) N36°W 46.9'



12" W. Spruce (1/2 S NBT) N28°E 61.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner has 6.0' west of read.

This corner re-established midway and on line bet. two Sec. cors.
Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1-21-72
REGISTERED LAND SURVEYOR