

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N.R. 6-7W


Mackinac COUNTY

DESCRIPTION OF CORNER South 1/16 Corner bet. Secs. 1-6

CORNER MONUMENT 1" pipe with 4" aluminum cap, buried in west wheel track of road.

DATE MONUMENT PLACED AND WITNESSED 10-29-64

WITNESSES TO CORNER..... 14" Hard Maple (BT) S60°W 28.9'



8" Hard Maple (BT) N80°E 22.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway bet. Sec. Cor. to south and $\frac{1}{2}$ Cor. to North.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 1-21-71
REGISTERED LAND SURVEYOR