

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N R. 7W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 5-6

CORNER MONUMENT 1" Pipe with 4" aluminum cap. Wood post.

DATE MONUMENT PLACED AND WITNESSED 1-13-71

WITNESSES TO CORNER..... 17" W. Birch (1/2 S NBT) N17°W 56.1'



8" W. Birch (1/2 S NBT) S69°E 25.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by proportionate measure and/or line bet. two Sec. Cors.
Found no evidence of original corner.
Corner lies in a low swampy area.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 1-22-71
REGISTERED LAND SURVEYOR