

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42N N. R. 7W


Mackinac COUNTY

DESCRIPTION OF CORNER North 1/16 corner bet. Secs. 5-6

CORNER MONUMENT 1" pipe with 4" aluminum cap. Wood post

DATE MONUMENT PLACED AND WITNESSED 1-13-71

WITNESSES TO CORNER..... 15" Cedar (N 1/16 BT) N4°E 61.0'



14" Cedar (N 1/16 BT) N73°E 40.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed on line and by proportionate measure bet. Sec. Cor. to north and $\frac{1}{4}$ Cor. to South.

Corner lies 402.0' South of C.L. US#2.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE 1-22-71
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR