

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N. R. 6-7 W


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs ' 6-7-1-12

CORNER MONUMENT 3/8" Iron Bar driven beside 2" Iron Pipe set in Concrete

DATE MONUMENT PLACED AND WITNESSED 8-19-1964

WITNESSES TO CORNER..... 12" Hard Maple (S7 NBT) S70°E, 18.3'



12" Hard Maple (S6 NBT) N38°E, 29.1'

AND

Corner lies on East edge of Trail Road.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-witnessed as set by D. Brotherton, Land Surveyor about 1915, during Alignment Survey of old U.S. #2.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 9-8-1964
REGISTERED LAND SURVEYOR