

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 42N R 7W

DESCRIPTION OF CORNER East 1/16 Cor. Section 4

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8-10-71

WITNESSES TO CORNER..... 18" Hard Maple (E 1/16 BT) N5°W 72.5'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed midway between East  $\frac{1}{4}$  Corner and center of section.  
Found a wood post 12.4' West and 4.0' South of Corner.  
Corner lies 51.0' North of Hwy. Centerline.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

9-22-71

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68