

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 42N R 7W

DESCRIPTION OF CORNER North 1/16 Cor. bet. Secs. 4-5

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8-10-71

WITNESSES TO CORNER..... 9" W. Birch (N 1/16 BT) N57°E 25.8'



12" W. Birch (N 1/16 BT) N37°W 23.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between Sec. Cor. to North and  $\frac{1}{4}$  Cor. to South.

Cor. lies on top of a steep hillside and 108.2' South of Hwy. Centerline.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*

Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE

9-22-71

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68