## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Mackinac Co.

2 Corners.

FOR CORNERS OF -:	LOCATED	1N -:		CORNER CODE NUMBER
I. PUBLIC LAND SURVEY	т. 42	N. R. 7	W.	Н-1
2. PROPERTY CONTROLL- 3 ING IN SECTION	т. 42	N. R. 7	_ K. V.	5
3. MISCELLANEOUS PROPERTY IN SECTION	- ,T	N. S., R	E. W.	
4. LOT NO, RECORDED PLAT				
S DRIVATE CLAIMS				

REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- 1 1/4 Corner on North side of Section 3. Corner was not set in original survey.

North 1/16 Corner of Section 3. Not prev. est.

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 1 Set corner midway on line between the NE and NW Section Corners of Section 3.

Set corner by single proportionate measure between the North 1/4 corner and the center 1/4 corner of Section 3.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- et D.N.R. monument at both corners. Bearings are:

SIGNED BY Davil B. Balkett

' DATE 12-21-81

David Eabbitt SURVEYOR'S MICHIGAN REGISTRATION NO. 21558

(SEAL)

FOR STATE AND UNITED STATES AGENCIES: