## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

MACKINAC CO.

3 Corners.

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	1
1. PUBLIC LAND SURVEY	T S., R W.		
2. PROPERTY CONTROLL- ING IN SECTION 10.	T. 42 §., R. 7 §.	H-4, H-4812, 5	
3. MISCELLANEOUS PROPERTY IN SECTION,	T N. E. W.		
4. LOT NO, RECOR	DED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER

- A. Description of original monument and accessories and/or subsequent restoration:
- H-4 Center of Section 10. Not prev. set.
- H-4&12 Property Corner on the North-South 1/4 Line of Section 10[635.19' South of the Center Cornei Not prev. set.
- 5 North 1/16 Corner of Section 10. Not prev. set.
  - B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- H-4 Set at the intersection of a line westerly, from the east 1/4 corner, parallel to the north section line with a line southerly, from the north 1/4 corner, parallel to the east section line of section 10. Said parallel lines are the 1/4 lines of section 10 because south and west lines of section 10 fall in Lake Michigan.
- H-4&12 Set on the North-South 1/4 line of section 10, 635.19' south of the center of section, on the shore of Lake Michigan.
- 5 Set M.P.O.L. between the center of section and the north 1/4 corner of section 10.
  - C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- D.N.R. Monuments set at all three corners.

H-4	6" W. Birch, S55°E, 41.3'	H-4&12 8"	Cedar, N10°E, 20.4'	5 12"	Cedar,	N7O°W,	154.75
	10" W. Birch, \$30°W, 6.4'	8"	Cedar, N71°E, 38.9'	12"	Cedar,	S13°W,	77.15"
	8" W. Birch, N79°W, 29.7'	9"	Cedar, S66°E, 36.0'	6"	Balsam,	N54°W,	136.04'
	6" R. Maple, NO1°E, 39.8'	6"	Cedar, S38°E, 12.5'	4"	Spruce,	S27°E,	29.65'

SIGNED BY Land B. Ballitt	DATE 1-23-87
bavid B. Babbitt	
SURVEYOR'S MICHIGAN REGISTRATION NO. 21558	_ (\$EAL)