

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970
 Mackinac Co. 1 Corner

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>42</u> ^{N.} X. , R. <u>7</u> ^{X.} W.	<u>F-1</u>
2. PROPERTY CONTROLLING IN SECTION _____	, T. _____, ^{N.} S. , R. _____, ^{E.} W.	_____
3. MISCELLANEOUS PROPERTY IN SECTION _____	, T. _____, ^{N.} S. , R. _____, ^{E.} W.	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 8/4, 1971, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

F-1 North Quarter Corner of Section 4. This corner was not set in the original survey. This is on a Township Line. Only the Quarter Corner for Sec. 33, T43N R7W was set.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

F-1 Corner placed 7.59' West of the South Quarter Corner, Section 33, T43N R7W.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1 Placed 1" pipe with 4" aluminium cap at the corner.

Bearings: 10" Hard Maple, S40°E, 29.3' and 8" Hard Maple, S39°W, 8.8'

Corner is 7.59' West of $\frac{1}{4}$ corner, Section 33, T43N R7W.

SIGNED BY Billy D. Buckler DATE 10-5-77
 Billy D. Buckler
 SURVEYOR'S MICHIGAN REGISTRATION NO. 8887



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY _____ DATE _____
MICHIGAN REGISTERED LAND SURVEYOR (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____