

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 42-43 N.R. 8 W.

Mackinac COUNTY

DESCRIPTION OF CORNER Section corner for Sections 34 and 35, T. 43 N. R. 8 W.
and Sections 3 and 2, T. 42 N. R. 8 W.
CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 5/1/63

WITNESSES TO CORNER..... 6" Cedar (S. 2) (N.B.T.) S. 60° E. 14 Lks.



7" Cedar (S. 34) (N.B.T.) N. 20° W. 37½ Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from old wood post.

No original evidence was found.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7-29-63
REGISTERED LAND SURVEYOR
Billy D. Buckler