

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42,43 N.R. 8 W.


Mackinac COUNTY

DESCRIPTION OF CORNER Meander Corner between Sections 34, T. 43 N., R. 8 W. and
3, T. 42 N., R. 8 W.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 5/1/63.

WITNESSES TO CORNER..... 8" Cedar (M.C.) (N.B.T.) S. 52° W., 32 Lks.



9" Cedar (M.C.) (N.B.T.) N. 11° E., 12 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from old wood post. No original evidence found.
Corner checks good for distance with section corner to East.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-5-63
Billy D. Buckler
REGISTERED LAND SURVEYOR