

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR 11-12 W.

Mackinac COUNTY

DESCRIPTION OF CORNER: Section corner common to Sections 30, 31, 25, 36.

DESCRIPTION OF CORNER MONUMENT: 1" Pipe with 4" Brass Cap.

WITNESSES TO CORNER: 4" Cedar (S 31 NBT) S 64° E 10 Links

8" Cedar (S 25 NBT) North 12 Links

9" Cedar (S 36 NBT) N 72° W 26 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced at old wood post set by unknown surveyor about 1924. Found lines of blazes in all four directions. No positive evidence of original corner. Corner lies in Cedar swamp.

Corner was placed and witnessed March 8, 1960 with R. Hinds.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/29/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler