

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY
T 42N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 28-29-32-33

CORNER MONUMENT 5/8" iron, in monument box

DATE MONUMENT PLACED AND WITNESSED 4-14-69

WITNESSES TO CORNER..... None



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Round this corner as placed during highway construction.

Cor. lies in center of a N-S road and in line with a fence to east.
There appears to have been an old road grade, following the south side of
this fence.

SURVEYOR'S SEAL

Billy D. Buckler

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

4-24-69

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing