STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Mackinas	COUNTY
		T 41-42N	R 11W
DESCRIPTION OF CORNER	t cerner bet. Secs. 5-32		
CORNER MONUMENT 10 x 3	36" iron pipe, buried in E-W	road	
DATE MONUMENT PLACED AN	D WITNESSED 4-17-69		
	12" Hard Maple (S NBT)	N49°E 42.6°	
N	lim Hard Maple (\$S NBT)		
42-11			
CIRCLE CORNER REGISTE	AND		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway bet. two Sec. Cors. Found ne evidence of eriginal corner.

SURVEYOR'S SEAL

SIGNED

Selly D. Buckler.

Billy D. Buckler

DATE 4-4

DISTRIBUTION: REGISTERED LAN

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing