

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 41-42N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 5-6-31-32

CORNER MONUMENT 1 1/4" x 30" iron pipe, driven in E-W Road

DATE MONUMENT PLACED AND WITNESSED 4-17-69

WITNESSES TO CORNER..... 9" cedar (S31 NBT) N20°W 86.1'



8" cedar (S32 NBT) N22°E 76.0

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced midway bet. two fence corners and in E-W Road. Fences are 58.0' apart.

Placed location post, 33' north.

SURVEYOR'S SEAL

*Billy D. Buckler*  
BILLY D. BUCKLER

SIGNED

REGISTERED LAND SURVEYOR

DATE

5-2-69

DISTRIBUTION:

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing