

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Mackinac COUNTY  
T 41-42N R 11W

DESCRIPTION OF CORNER West 1/16 corner bet. Secs. 6-31

CORNER MONUMENT 1" x 36" iron pipe, buried in road.

DATE MONUMENT PLACED AND WITNESSED 4-17-69

WITNESSES TO CORNER..... 18" Hard Maple (BT) N67°E 72.8'



AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced in line with fence to north and 29.0' south of fence corner.  
Corner lies in road, near north edge.

Placed location post 33' north.

SURVEYOR'S SEAL

SIGNED

*Billy D. Buckler*  
Billy D. Buckler

DATE

5-2-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing