

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD

Mackinac COUNTY


T 41-42N R 11W

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 6-31

CORNER MONUMENT 1" x 36" iron pipe, buried in E-W road

DATE MONUMENT PLACED AND WITNESSED 4-17-69

WITNESSES TO CORNER..... 6" cedar (NBT) S40°E) 37.5'



8" cedar (1/8 NBT) S22°W 53.7'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner replaced midway between two fence corners, which are 58.0' apart and in center of an E-W road.**

SURVEYOR'S SEAL

*Billy D. Buckler*

SIGNED

Billy D. Buckler

DATE

4-24-69

DISTRIBUTION:

REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing