MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_42_ NR_12 W __

				Meckine	a <u>c</u>	_ COUNTY
DESCRIPTION	OF	CORNER	_Section Corn	er_common_to_S	ections 8, 9,	<u>1</u> 6, 17
DESCRIPTION	OF	CORNER	MONUMENT	lm pipe with	4 ⁿ brass cap _	
WIT TNESSES	то	CORNER	2"_Cedar	s_30°_E	30 links	
			8" Cedar	North	51 links	
					. .	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from one Cedar B.T. in good condition.

Corner shown to us by James Halbach, District Forester.

Corner placed and witnessed March 9, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 3/19/56_
REGISTERED LAND SURVEYOR