

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 12W.

Mackinac COUNTY

DESCRIPTION OF CORNER Sec. Cor. 20-21-28-29

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 4" Cedar (S21 NBT) N75°E 33 Lks.

4" Cedar (S20 NBT) N21°W 25 Lks.

6" Aspen (S28 NBT) S07°E 22 Lks.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Cor. from one Cedar stp. (Probable B.T.) bearing s83°W
17 Lks. Found rotted face and overgrowth on stp. Position fits
well with swamp edges. Cor. placed and wit. 6/5/59 with B.
McDonald, Aide.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 7/29/59
REGISTERED LAND SURVEYOR