MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 42 NR 12W

Mackinac COUNTY
DESCRIPTION OF CORNER Sec. Cor. for Secs: 10-11-14-15
DESCRIPTION OF CORNER MONUMENT1" Pipe with 4" Brass Cap
WITNESSES TO CORNER Z"_Cedar_(Sll_NBT) N50°E _ 21 Lks.
9" Cedar (S10 NBT) N82 W 26 Lks.
·

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced from two W. Birch B.Ts. bearing N40°E 17 Lks. tree down, badly rotted. Found calloused overgrowth of both faces, Stp. bottom bearing S72°W 10 Lks. Old cruisers tree 02 Lks. southeast of cor. Many names and dates. Cor. lies in swamp and 07 Lks. east of N-S transit line. Cor. placed and wit. 5/8/59 with J. Halbach, D.F.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7/29/59