

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42. NR. 12. W

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 29 and 32

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Beech (1/4s NBT) S 42° E 55 Links

6" Twin Cedar (1/4s NBT) S 25° W 83 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. This corner was re-established midway and on line between two Section corners. No evidence of original corner.

Corner was placed and witnessed September 18, 1959 with Frank Bray.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/29/60