

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T~~41~~-42 NR 12 W

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Section corner for Section 32, T 42 N, R 12 W  
and Section 5, T 41 N, R 12 W

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 5" Cedar (1/4s NBT) S 52° E 13 Links

7" Cedar (1/4s NBT) N 24° W 48 Links

7" Cedar (1/4s NBT) N 40° E 56 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. This corner was replaced from old wood stake set by unknown party.  
Corner lies in thick cedar and spruce swamp.

Corner was placed and witnessed September 17, 1959.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/29/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler