

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 42 .. NR 11 & 12 W

M a c k i n a c COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 31 and 36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Cedar (1/4" NBT) N 62° E 29 Links

10" Cedar (1/4" NBT) S 10° E 24 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was placed midway and on line between section corners.

Remarks:

Found old blazes at corner.

Corner was placed and witnessed September 1, 1960.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 9/15/60
REGISTERED LAND SURVEYOR
Billy D. Buckler