

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 42N N. R. 12W
Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 28-29

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-19-62

WITNESSES TO CORNER..... 9" cedar (1/4 S NBT) N25°W, 13 1/2 links



5" Cedar (1/4 S NBT) S60°W, 26 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established midway and on line between two section corners. No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler