

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 12W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 1 20-29

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 1/9/64

WITNESSES TO CORNER..... 10" Balsam ($\frac{1}{2}$ S NBT) S21°E 31 lks.



12" W. Spruce ($\frac{1}{2}$ S NBT) N28°W 21 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two Section Corners.
Found no evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler.
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR

DATE 7/30/1964