

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 N.R. 12, 13 W


Schoolcraft & Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 7-12.

CORNER MONUMENT 1" Iron Pipe & 3/4"x16" Iron Pin buried in Center of N-S Road.

DATE MONUMENT PLACED AND WITNESSED 11-10-69

WITNESSES TO CORNER..... 9" Hard Maple (1/2 NBT) N62°W 47.2'



14" Elm (1/2 NBT) S81°E 88.9'

Metal Fence Post East 16.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced and rewitnessed as placed by unknown land surveyor. Found the 1" Iron pipe bent over on road surface. Drove this pipe down and placed an Iron Pin alongside.

Corner lies in a N-S road and in a line of trees to East.

SURVEYOR'S SEAL

Billy E. Buckler.
SIGNED Billy E. Buckler DATE 1-12-70
REGISTERED LAND SURVEYOR