

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 42 N N.R. 12 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner Between Sections 17-18

CORNER MONUMENT 1 inch iron pipe with 4 inch Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 11-10-69

WITNESSES TO CORNER..... 10 inch Soft Maple ( $\frac{1}{4}$  S NBT) N56°E 34.1°



10 inch Cedar ( $\frac{1}{4}$  S NBT) S28°E 28.8°

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner reestablished midway and on a line between two sections corners. Found no evidence of original corner or witnesses.

Corner lies 38.0° East of North-South Grade and 69.0° South of old road to the West.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE 12-30-69  
Billy D. Buckler  
REGISTERED LAND SURVEYOR