

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 43N N.R. 1W


Mackinac COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 27-28-33-34

CORNER MONUMENT 5/8" iron rod, driven in intersection

DATE MONUMENT PLACED AND WITNESSED 8-5-69

WITNESSES TO CORNER..... Stop Sign N27°W 46.7'



" " N69°E 55.8'

" " S20°E 58.8'

AND " " S69°W 62.9'

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed in intersection of county road, in all four directions.  
Found no evidence of corner here.  
Used this corner to re-establish a corner, one mile north.

SURVEYOR'S SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler  
REGISTERED LAND SURVEYOR

DATE 1-20-71