

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43N N.R. 1W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner bet. Secs. 2-35

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-18-67

WITNESSES TO CORNER..... 12" Cedar (1/4 S MBT) S62°E 30.5'



7" Cedar (1/4 S MBT) North 27.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one original B.T.; a Y. Birch, bearing N44°W, 11 links;
tree green and in good condition, with faces rotting.

Single wire fence, running north and east.
Corner lies in low, wet land.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

4-2-70