SURVEY & REMONUMENTATION

JAN 21 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Mackinac County Remonumentation Corner

For corners in

Mackinac County	Located	in:	•	Corner Code #
1. Public Land Survey		T43N T T T	R01W R R R	H-11
	S S	T T	R R	
3. Miscellaneous	S S	T T	R R	

RECEIVED & FILED

DIANE FRANKOVICH MACKINAC COUNTY REGISTED OF DECDS

DEC 3 1 1993

21819119111112111213141516

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat


5. Private Claims

I, Neil E Hill, in a field survey on 12-21-98, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1845 GLO Notes William A Burt	20" Sugar	N 44 E	21 lks
	4" Sugar	S 15 W	21 lks
1994 R Bischer Fd ½" Rod Liber D, Page 264	10" Maple 8" J Pine 3" J Pine 10" Maple	N 05 W S 36 E S 38 W N 46 E	59.30 ft 50.40 ft 69.05 ft 65.50 ft



ACCEPTED BY THE MACKINAC COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER PA. 345 OF 1990 AT A MEETING 12-04-98 HELD ON NEH

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998 Fd 1/2" rod and 4 witnesses Accepted corner location

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 1/2" bar in E-W road

N 05 W	59.40'
S 25 E	20.29'
S 38 W	69.05'
N 50 E	65.56'
S 10 E	50.00'
	S 25 E S 38 W N 50 E



Bearings are compass bearings, corrected for declination, all distances are to a double-headed nail in the side of the witness object unless otherwise noted.

Signed by

Date

Surveyor's Michigan License No. 27447

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995