

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 6 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 16 and 17

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 6/20/61

WITNESSES TO CORNER.... 8" Cedar (1/4S NBT) N 85° W 08½ Links



8" Cedar (1/4S NBT) S 28° E 43½ Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from W. Pine Stump bearing S 73° W, 82 Links (possible bearing tree). Found old blazes to North, South and West. Distance North to Stream 3.00 chains check good. Corner lies 4 chains East of Road, Placed location post on Road.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE July 26, 1961