

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR. 6 W.

Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 21-22

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 7" Cedar N 43° W 10 links

"1/4 S NBT"

7" Cedar S 66° W 17 links

"1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from one tamarack B.T. bearing S 89° W 06 links.
B.T. down and in good condition.

1/4 corner lies in wet cedar swamp.

Corner found by J. Halbach, District Forester.

Corner placed and witnessed December 26, 1957.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 1/13/58