

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 6 & 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for Sections T43N 1/6 T43N R7W R6W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/27/66, Frank J. Bray with J. Price

WITNESSES TO CORNER..... 8" Cedar (1S)(NBT) N 51° E. 04 Links



7" Cedar (1S)(NBT) S 16° E. 16 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was - placed midway and on Line between Section Corners 1/2 mile to south and to North. No original evidence found. Blazed Cedar in near vicinity.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/19/67  
REGISTERED LAND SURVEYOR