

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 43 N. R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for Sections ¹⁶/₂₁

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/29/66, Frank J. Bray

WITNESSES TO CORNER..... 10" Cedar (1/4S)(NBT) S 31° W, 45 Links



7" Cedar (1/4S)(NBT) N 35° E, 40 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was - replaced from cedar stump (10" cedar S 54° E, 20 Links) original BT rotted over growth of scribe marks and notch visible.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/25/67
REGISTERED LAND SURVEYOR