

✓

**MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION**

LAND CORNER RECORD

T. 43 N. R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER E 1/16 corner for Sections $\frac{12}{13}$

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 6/2/66, Frank J. Bray and R. Lane

WITNESSES TO CORNER..... 8" Cedar (E 1/16)(BT) S 30° E, 30 Links



8" Cedar (E 1/16)(BT) N 62° E, 18 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between Section Corner to East and 1/4 corner to West.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/25/67
REGISTERED LAND SURVEYOR