

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N. R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for Sections <sup>23</sup>/<sub>26</sub>

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/18/67, Frank J. Bray

WITNESSES TO CORNER..... 5" Cedar (1/4S)(NBT) N 20° W, 10 1/2 Links



6" Cedar (1/4S)(NBT) S 35° W, 08 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was - placed midway and on line between Section corners 1/2 mile to East and West. No original evidence.

SURVEYOR'S SEAL

SIGNED

*Frank J. Bray*  
Frank J. Bray

REGISTERED LAND SURVEYOR

DATE

7/25/67