

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 13 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER E 1/16 for Sections ²³/₂₆

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/18/66, Frank J. Bray

WITNESSES TO CORNER..... 6" Cedar (E 1/16)(BT) S 05° E, 11 Links



8" Cedar (E 1/16)(BT) N 81° W, 22 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was - placed midway and on line between section corner to East and 1/4 corner to West.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/25/67
REGISTERED LAND SURVEYOR