

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION



# LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER S 1/16 corner for sections 23/24

CORNER MONUMENT 1" iron pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/3/66 - F. J. Bray

WITNESSES TO CORNER..... 7" cedar (S 1/16) (BT) S 66° E, 14 links



6" cedar (S 1/16) (BT) N 83° W, 30 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corner to south and  $\frac{1}{4}$  corner to north.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/19/67  
REGISTERED LAND SURVEYOR  
Frank J. Bray