

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 corner for sections 30/29

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/16/67, Frank J. Bray

WITNESSES TO CORNER..... 6" Cedar (1/4S)(NBT) N 55° E, 12½ Links



CIRCLE CORNER REGISTERED

10" Cedar (1/4S)(NBT) S 32° W, 17½ Links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between section corners 1/2 mile to North and to South. Blazed Cedar near. No original evidence.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/31/67  
REGISTERED LAND SURVEYOR