

✓

**MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION**

# LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER Section corner for sections  $\frac{17}{16}$   
 $\frac{20}{21}$

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 5/16/67, Frank J. Bray

WITNESSES TO CORNER..... 5" Spruce (S17)(NBT) N 15° W, 20 Links



7" Cedar (S21)(NBT) S 48° E, 86 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was - reestablished by double proportioned measurement between 1/4 corner 1/2 mile to East. Section corners 1 mile to North, South and to West.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/31/67  
REGISTERED LAND SURVEYOR