Cans. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

	Mackinac	COUNTY
DESCRIPTION OF CORNER + corner for Sec. 5 TASK RS	1 36-31 TA3N R7W	
CORNER MONUMENT 1" Iron Pipe with 4" Alumina	па Сар	
DATE MONUMENT PLACED AND WITHESSED	Bray	
WITHESSES TO CORNER 11" Codar (15) (NBT) S 34	W, 107 Links	<del></del> .
6* Cedar (in clump) (1/2S)	(NBT) N 67° W, 813 Links	
AND  CINCLE CORNER RESISTERED		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between Section Corners  $\frac{1}{2}$  mile to north and to south,

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/18/67