

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 & 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections ³¹ T43N R7W
6 T42N R7W

CORNER MONUMENT _____

DATE MONUMENT PLACED AND WITNESSED 5/24/67, Frank J. Bray

WITNESSES TO CORNER..... 5th Cedar (1/8)(NBT) N 38° E, 21 Links



7th Cedar (1/8)(NBT) N 67° W, 28 Links

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed on line and single proportioned measurement between Section Corners to East and to West. Corner Falls in grown in winter logging road running East and West.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 7/18/67
REGISTERED LAND SURVEYOR