

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W.


Mackinac COUNTY

DESCRIPTION OF CORNER Section corner for Sections 31 and 32.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap inserted in 1½" pipe.

DATE MONUMENT PLACED AND WITNESSED 5/1/63.

WITNESSES TO CORNER..... 12" Cedar (S. 32)(N.B.T.) N. 42° E., 23½ Lks.



9" Cedar (S. 31)(N.B.T.) N. 09° W., 25½ Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 1½" iron pipe and wood post and is 21 Lks.
East of C.C. of Sections 5 and 6 as recorded in original notes.
No original evidence found.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 8-5-63
REGISTERED LAND SURVEYOR