

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W.


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 25-26-35-36.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 3/21/63

WITNESSES TO CORNER..... 8" Cedar (S. 26 N.B.T.) N. 48° W, 43 Lks.



8" Cedar (S. 36 N.B.T.) S. 54° E. 22½ Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as found and marked by Marcus Schaaß,
Registered Land Surveyor. Found remains of one Tamarack B.T.

Corner lies in thick cedar swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7/29/63
REGISTERED LAND SURVEYOR
Billy D. Buckler