

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 7W


Mackinac COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 23, 24, 25 and 26.

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 3-21-63.

WITNESSES TO CORNER..... 7" Cedar (S. 25 N.B.T.) S. 47° E., 23 Lks.



7" Cedar (S. 23 N.B.T.) N. 43° W., 27 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced as found and marked by Marcus Schaaf,  
Registered Land Surveyor. Found post and one Tamarack B.T.  
to North-West of Corner.

Corner lies in thick cedar swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/11/63  
REGISTERED LAND SURVEYOR