Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W

			Mackinac		COUNTY
SCRIPTION OF CORNER Section Corner for Sections 13-14-23-24					
CORNER MONUMENT	l" Pipe with L	Brass Cap	<u> </u>	<u>-</u>	<u> </u>
DATE MONUMENT PLACED AND	VITNESSED <u>1-30-</u>	62 with Mar	rcus Burnis,	Aide	
VITMESSES TO CORNER	<u>5° Cedar</u>	N 25° W	(S1) NBT)	17 links	
N24	12ª Cedar	N 314° E	(S13 NBT)	h0 links	
CIRCLE CORNER REGISTERED	AND				

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced as set by Marcus Schaaf, Reg. Land Surveyor. Found Iron Pipe and Wood Post. Found Cedar Stub bearing S 62° E 18 links for B.T. according to notes by Schaaf.

SURVEYOR'S SEAL

SIGNED Suches DATE 10-28-63

RESUSTERED LAND SURVEYOR
Filly D. Buckler