

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 N.R. 7 W


Mackinac County COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 4-5-32-33

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9-25-62

WITNESSES TO CORNER..... 8" W. Pine (S 32 NBT) N 46° W 49½ links



6" W. Pine (S 33 NBT) N 51° E 59 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced at iron pipe set by Marcus Schaaf, Registered Land Surveyor.

Found no evidence of original corner but found wood stake with Iron Pipe and concrete square set by Schaaf.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64
REGISTERED LAND SURVEYOR
Billy D. Buckler