

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER 1/4 Corner on South Side of Section 33

CORNER MONUMENT 1" Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 11-28-62

WITNESSES TO CORNER..... 10" Y. Birch (1/4 S 33 NBT) N 23° E 61 links



10" Hard Maple (1/4 S 33 NBT) N 81° W 36 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner re-established midway and on line between two Section Corners.

No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64
REGISTERED LAND SURVEYOR
Billy D. Buckler