

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 7 W


Mackinac COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 20-21-28-29

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9-26-62

WITNESSES TO CORNER..... 12" Red Pipe (S 20 NBT) N 72° W 58 links



10" " " (S 29 NBT) S 20° W 100 links

10" " " (S 28 NBT) S 62° E 93 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed in intersection of roads West, South and Northeast.

Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 4-2-64
REGISTERED LAND SURVEYOR
Billy D. Buckler